



Surface

Diagram illustrating the dimensions of a stepped shaft. The shaft consists of a series of steps with varying diameters and lengths. The dimensions are as follows:

- Step 1: Diameter $\varnothing 100\text{mm}$, Length 220mm
- Step 2: Length 400mm
- Step 3: Length 600mm
- Step 4: Length 800mm
- Step 5: Length 1000mm
- Step 6: Length 1200mm

Accessories

